

AD-A072 795

BERGER ASSOCIATES INC HARRISBURG PA

F/6 13/2

NATIONAL DAM INSPECTION PROGRAM. CORNWALL TAILINGS DAM (NDI NUM--ETC(U)

JUL 79

DACW31-79-C-0012

NL

UNCLASSIFIED


| OF |

AD  
A072795



END  
DATE  
FILMED  
9-79

DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

LEVEL *X*

A072795

**SUSQUEHANNA RIVER BASIN**


**CORNWALL TAILINGS DAM**

NDI NO. PA-00597

DER NO. 38-87

LEBANON COUNTY, PENNSYLVANIA ✓

**PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**



DDC  
RECEIVED  
AUG 17 1979  
REGISTRY

DDC FILE COPY

PREPARED FOR  
DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

Contract # DACW31-79-C-0012

BY

Berger Associates, Inc.  
Harrisburg, Pennsylvania

JULY 1979

This document has been  
for public release and  
distribution is unlimited

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.  
THE COPY FURNISHED TO DDC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.

79 08 15 068

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**



## PREFACE

This report has been prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

79 08 15 068

This document has been approved  
for public release and sale; its  
distribution is unlimited.

15

DACW31-79-C-0012

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITIONS  
AND RECOMMENDATIONS

Name of Dam: CORNWALL TAILINGS DAM, NDI NO. PA-597  
State & State No: PENNSYLVANIA, 38-87  
County: LEBANON (6) National Dam Inspection Program, Cornwall  
Stream: BERNHARD CREEK Tailings Dam (NDI Number PA-00597, DER  
Date of Inspection: May 11, 1979 Number 38-87), Susquehanna River Basin,  
Bernhard Creek, Lebanon County,  
Pennsylvania, Phase I Inspection Report.

Based upon the visual inspection and the available engineering data, the dam and its appurtenant structures appear to be in good condition.

Hydrologic and hydraulic calculations indicate that the present reservoir has sufficient storage capacity to handle the inflow of the Probable Maximum Flood without overtopping the dam. It is considered that the storage capacity is adequate. It has been estimated that the yearly evaporation and leakage equals the annual inflow and that, as a result, an increase in the normal pool level is very unlikely.

The following recommendations are made for action by the owner:

1. That a staff gauge be installed on the decant tower located in the pool and that at least monthly readings be taken to establish records of changes in the pool level.
2. That the 6-inch blowoff valve on the decant pipe be located and made operable for use in the event of an emergency.

(12) 82 P

(11) Jul 79

79 08 15 068

417 003

set

3. That a formal surveillance and downstream warning system be developed for implementation during periods of heavy or prolonged precipitation.

SUBMITTED BY:

BERGER ASSOCIATES, INC.  
HARRISBURG, PENNSYLVANIA

DATE: July 13, 1979




APPROVED BY:

*James W. Peck*  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer

DATE 28 July 1979

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification for	<input checked="checked" type="checkbox"/>
By	<i>on file</i>
Distribution/	
Availability Codes	
Dist	Avail and/or special
<i>A</i>	<i>23</i> <i>SEC</i>

79 08 15 068



OVERVIEW  
CORNWALL TAILINGS DAM

## TABLE OF CONTENTS

	<u>Page</u>
SECTION 1 - <u>PROJECT INFORMATION</u>	
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
SECTION 2 - <u>ENGINEERING DATA</u>	
2.1 DESIGN	5
2.2 CONSTRUCTION	6
2.3 OPERATION	6
2.4 EVALUATION	6
SECTION 3 - <u>VISUAL INSPECTION</u>	
3.1 FINDINGS	8
3.2 EVALUATION	9
SECTION 4 - <u>OPERATIONAL PROCEDURES</u>	
4.1 PROCEDURES	10
4.2 MAINTENANCE OF DAM	10
4.3 MAINTENANCE OF OPERATING FACILITIES	10
4.4 WARNING SYSTEM	10
4.5 EVALUATION	10
SECTION 5 - <u>HYDROLOGY/HYDRAULICS</u>	
5.1 EVALUATION OF FEATURES	11
SECTION 6 - <u>STRUCTURAL STABILITY</u>	
6.1 EVALUATION OF STRUCTURAL STABILITY	12
SECTION 7 - <u>ASSESSMENT AND RECOMMENDATIONS</u>	
7.1 DAM ASSESSMENT	15
7.2 RECOMMENDATIONS	15
APPENDIX A - CHECK LIST OF VISUAL INSPECTION REPORT	
APPENDIX B - CHECK LIST OF ENGINEERING DATA	
APPENDIX C - HYDROLOGY AND HYDRAULIC CALCULATIONS	
APPENDIX D - GEOLOGIC REPORT	
APPENDIX E - PHOTOGRAPHS	
APPENDIX F - PLATES	



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

CORNWALL TAILINGS DAM

NDI-ID NO. PA-00597

DER-ID NO. 38-87

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

A. Authority

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspections of dams throughout the United States.

B. Purpose

The purpose is to determine if the dam constitutes a hazard to human life and property.

1.2 DESCRIPTION OF PROJECT

A. Description of Dam and Appurtenances

Handwritten: *As noted*  
Cornwall Tailings Dam was constructed by the Bethlehem Mine Corporation as a settlement basin for their tailings from a nearby iron ore mine operation. The mine was closed in 1977 and the facilities of the dam are presently not in use. At the time of inspection, it was estimated that the top of the dam is approximately at elevation 908 and the pool level was at elevation 890. The U-shaped embankment is 3800 feet in length. (Refer to ~~Plate III~~, Appendix F). The northern part of the embankment, which spans the original valley, is about 1900 feet long and has a maximum height of 200 feet above the downstream toe. The remainder of the embankment closes off lower areas on the east side of the reservoir with heights varying up to 60 feet. Most of the embankment was constructed from trap rock, with the exception of an impervious upstream toe and upstream blanket. There is no spillway. The only outlet is a 20-inch decant line which returned water to the mine. At present, this line is closed off near the downstream toe. *Handwritten: AS NOTED*

B. Location:

Cornwall Borough, Lebanon County  
U.S.G.S. Quadrangle, Lebanon, PA  
Latitude 40°-16.5', Longitude 76°-22.8'  
(Appendix F, Plates I and II)



- C. Size Classification: Large (200 feet high, 667 acre-feet)
- D. Hazard Classification: High (Section 3.1.E)
- E. Ownership: Bethlehem Mines Corporation  
Martin Tower  
Bethlehem, PA 18016
- F. Purpose of Dam: Settlement basin for mine tailings
- G. Design and Construction History

Cornwall Tailings Dam was designed by the Bethlehem Cornwall Corporation, a subsidiary of Bethlehem Steel Corporation. The foundation investigation, soils and geologic report, stability and seepage analysis were prepared by E. D'Appollina Associates, Pittsburgh, Pennsylvania. The permit for construction was issued on March 6, 1961, and actual construction started in April of that year. The contractor, Reisinger Bros., Inc., Carlisle, Pennsylvania, completed the initial phase of construction in October, 1961. This construction was limited to an embankment length of about 700 feet, and to a finished crest elevation of 805 (Plate VI, Appendix F). This initial phase was constructed of impervious material and is now incorporated in the dam as the upstream toe.

The subsequent raising of the dam to the design crest elevation of 910 was constructed by the owner when additional tailing storage was required.

#### H. Normal Operating Procedures

The tailing pond is not in use at the present time. Representatives of the owner stated that the reservoir water level has dropped since becoming inactive due to evaporation and seepage.

### 1.3 PERTINENT DATA

#### A. Drainage Area (square miles)

From files: 0.16

Use: 0.16

#### B. Discharge at Dam Site (cubic feet per second)

See Appendix C for hydraulic calculations

Maximum known inflow, June 22, 1972 from records for the U.S.G.S. gaging station on a nearby creek

230

	Outlet works at pool Elev. 889.7 (presently inoperative)	28
	Spillway capacity	No Spillway
C.	<u>Elevation</u> (feet above mean sea level)	
	Top of dam	908
	Spillway crest	No Spillway
	Streambed at toe of dam - estimate from inspection survey	708
D.	<u>Reservoir</u> (miles)	
	Length of pool	0.3
E.	<u>Storage</u> (acre-feet)	
	Top of dam (Elev. 908.0)	
	Tailings	3,213
	Water (estimated)	667
	Present pool level (Elev. 889.7) Water surface estimated from inspection survey	40
F.	<u>Reservoir Surface</u> (acres)	
	Top of dam (Elev. 908.0)	62
	Present level (Elev. 889.7) (estimated water area)	12
G.	<u>Dam</u> (See Appendix F, Plates III through VIII for details.	
	Type: Rockfill with impervious upstream blanket.	
	Length: 3,800 feet.	
	Height: 200 feet.	
	Top Width: Main embankment - 100 feet. Other sections - 30 feet.	

Side Slopes: \* Design (See Plate IV, Appendix F)  
Upstream: 2H to 1V  
Downstream: 1.75H to 1V with one berm.

Survey (See Plate A-II, Appendix A)  
Upstream: All covered with tailings (silt)  
to elevation 903±.  
Downstream: Varies between 1.1H to 1V and  
1.7H to 1V. Several wide berms.  
Average slope from top to toe  
1.95H to 1V (Waste Rock 4"±).

Zoning: Impervious upstream toe to elevation 805 and a 10  
foot impervious blanket above that elevation as per  
design drawings.

Impervious Core: None, see Zoning.

Cutoff: None. An intercepting lateral 8-inch seepage drain  
was installed under the embankment, backfilled with  
reject rock. This drain outlets through a 12-inch  
drain near the toe of the dam.

Grouting: None.

#### H. Outlet Facilities

At the present time, the only operating outlet from this  
reservoir is the underdrain of the dam embankment. This drain  
discharges about 0.3 cfs to Bernhard Creek. The drain is  
uncontrolled.

When the mine was operating (prior to 1977), the water level  
in the reservoir was controlled by the tailings deposit system.  
A pipe running along the top of the dam discharged a mixture  
of water and mine tailings into the reservoir. Decant towers  
at the upstream end of the reservoir collected the clear water  
and returned it to the mine workings via a 20-inch welded  
steel pipe. This pipe is now shut off and buried. If feasible,  
overflow for the reservoir could be provided by uncovering the  
20-inch pipe. The water would return to Bernhard Creek via an  
an existing ditch.

#### I. Spillway

This dam does not have a spillway.

#### J. Regulating Outlets

See Section 1.3.H.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

#### A. Hydrology and Hydraulics

The files of Pennsylvania Department of Environmental Resources (PennDER) or the files of the owner did not contain information concerning the hydrologic and hydraulic design of this dam. Due to the small drainage area, the function of the reservoir, and the presence of a 20-inch return line to the mine, a hydraulic analysis was not performed.

#### B. Embankment

The preliminary design of the embankment and the subsurface soils investigation was prepared by E. D'Appolinia Associates, Pittsburgh, Pennsylvania. A report written by this company includes a geologic report, seepage calculations and stability analysis for the main embankment. Based on this report, Bethlehem Cornwall Corporation prepared the design drawings. The embankment was constructed in several phases. The first phase consisted of an impervious embankment with a crest elevation of 805 (Plate VI, Appendix F) and the placing of an 8-inch seepage drain under the future extension of the embankment. This lateral 8-inch drain discharges into a 12-inch drain running to the downstream toe. A 24-inch pipe was installed under the embankment as a temporary diversion. This pipe was filled with lean concrete after the first phase was completed. Mine waste was brought to the reservoir through a 12-inch pipe. The clear water was taken from the reservoir at decant towers through a 20-inch pipe. This pipe would be extended upstream in the reservoir with additional decant towers if tailings would cover the first two constructed decant towers. When the decant tower was abandoned, the 20-inch pipe inlet was sealed with a steel plate and part of the tower was plugged with concrete. The 20-inch decant line led to a valve house near the downstream toe. A 6-inch pipe with a valve is tapped into the line and could be used for minimum flow requirements in Bernhard Creek. The 20-inch pipe was reduced to a 16-inch pipe in the valve house and could be closed off with a valve on this pipe. This 16-inch pipe was the return line to the mine.

The report on "Design Consideration" for this dam by E. D'Appolinia considered flow net patterns under the dam for the condition with a pool level of 739 and no sedimentation. The estimated seepage was 25,600 gallons per day. Another flow net using a pool level of 820 with tailings up to elevation 815 indicated a seepage flow of 2,000 gallons a day, due to the sealing effect of the tailings. The downstream design slope was 1.75H to 1V and one berm giving a factor of safety against sliding of the downstream slope of 4.13. The report stated that the material probably would stand to a slope of 1.5H to 1V. All pipes under the dam were placed on concrete pads and have antiseepage collars.

### C. Appurtenant Structures

This facility has no spillway and the only appurtenant structures are the decant towers and a 20-inch decant pipeline with valve house. See previous section for discussion.

## 2.2 CONSTRUCTION

Progress reports in the PennDER files indicate that the first phase was constructed as shown on Plate VI, Appendix F. The dam was raised to its final elevation in stages as required for tailing storage or as waste rock was available. Construction records are not available. A photograph taken in 1970 shows two 6-inch pipes projecting out of the slope about 20 feet above the toe having a small discharge. Origin of water is unknown and these pipes were dry at the time of the inspection. Additional decant towers were constructed and the 20-inch pipe was extended as needed.

## 2.3 OPERATION

Records of operation were not located and the facilities are not in use at the present.

## 2.4 EVALUATION

### A. Availability

The available information was obtained from the files of PennDER and include a design report, construction drawings, and construction specifications for the first phase. Some of this information is also available in the offices of the owner.

### B. Adequacy

#### 1. Hydrology and Hydraulics

No information was located concerning the hydrologic and hydraulic design for this dam. Other available information and the visual inspection are, however, considered sufficient to review the adequacy of the structure.

#### 2. Embankment

The available information is considered to be sufficient to review the design criteria and analysis of the embankment.

#### 3. Appurtenant Structures

The information located in the PennDER files are considered to be adequate to review the design of these structures.



C. Operating Records

There are no operating records on file with D.E.R. or the owner.

D. Post Construction Changes

The construction permit was issued for a dam with a maximum height of 158 feet and a crest elevation of 910. Refer to Section 1.2.G for design and construction history. The embankment was constructed in stages over some 15 years and although variations occurred from the original drawings, the main elements were not changed.



### SECTION 3 - VISUAL INSPECTION

#### 3.1 FINDINGS

##### A. General

The general appearance of Cornwall Tailings Dam is good. The reservoir, constructed by Bethlehem Steel Corporation as a settlement basin, is not in active use at the present time. Only a small pool of water exists in the south end of this reservoir. The depth of the reservoir is unknown and can only be estimated. It appears that a large amount of storage is available. There is no spillway or functionable discharge line. At the time of inspection, the pool level was about 18 feet below the top of the dam.

The inspection team was accompanied by two representatives of the owner during part of the time. The visual inspection check list is in Appendix A of this report. Photographs taken during the inspection are reproduced in Appendix E.

##### B. Embankment

The crest of the dam is about 3,800 feet long and is U-shaped (see Appendix F, Plate III). The highest section of the abutment is located at the north end of the reservoir. A typical section was surveyed and a schematic plan and survey section is shown in Appendix A, Plates A-I and A-II. A crest profile was not made during the inspection.

The main section has a crest width of about 98 feet, appears to be level and well compacted and is covered with grass and small weed growth. The upstream slope is mostly covered with silt deposits and slopes gently to the water surface about 600 feet upstream from the crest. The 98 foot wide crest has a rock dike at the downstream side, over most of its length. This rock pile is about 3 feet high and presumably was constructed as a safety barrier for trucks.

The downstream slope is steep (Plate A-II) and has several benches of variable width. The slope is all exposed waste rock (Appendix E, Plate E-1). The height of the fill at its maximum section is about 200 feet. Some water was seeping out of the embankment near the drain pipe which has been installed under the fill. The estimated flow is .3 cfs.

The major length of the dam has an estimated height from 30 to 60 feet maximum and has a similar rock dike and downstream slope.

### C. Appurtenant Structures

As previously mentioned, this dam does not have a spillway. The fine (silt) crusher waste of the mine was pumped to the reservoir through a 12-inch pipe. After the silt settled out, the clear water was returned to the mine for reuse by gravity through a 20-inch welded steel pipe.

Two intake decant towers are still visible. Both towers have an open flange 20-inch pipe through which the water could enter if the pool level would reach the invert elevation. A valve house was located near the downstream toe from which a 6-inch tap line could discharge water into an open ditch to the natural stream. This valve house was destroyed by vandalism and the owners have filled the valve pit with sand and gravel to prevent unauthorized use of the valves. The location of the valve pit is known to the owners.

### D. Reservoir Area

The reservoir area is mostly banks formed from silt with some brush growth. The drainage area is wooded outside of the actual reservoir.

### E. Downstream Channel

The downstream channel is the natural stream (Bernhard Creek) with several houses close to the stream and close to the embankment fill. About 2,000 feet downstream from the dam, the stream runs through the town of Rexmont with several homes located close to the stream. If the dam would fail due to overtopping, it is expected that the hazard to loss of life would increase. The hazard category for this dam is considered to be "High".

## 3.2 EVALUATION

The general appearance of the dam is good. The available storage in the reservoir is considerable for the size of the drainage area (less than .2 square miles). Based on the visual inspection it appears very unlikely that the reservoir would ever fill. Evaporation and normal leakage will probably control the pool level. The length of the embankment, the width of the crest and type of rock on the downstream slope all indicate that a relatively large outflow could be handled over the embankment without a chance of failure. Calculations to confirm any of these assumptions have not been made.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURE

Bethlehem Steel Corporation closed the mining facilities near Cornwall in 1977 and no active use is being made of this reservoir. At present, there are no operational procedures for this facility.

### 4.2 MAINTENANCE OF DAM

Maintenance is not being performed at the dam. The downstream slope has a rock surface without any growth at the present time. The crest of the dam is either bare stone and gravel or overgrown with low weeds.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The only operating facilities are the two decant towers and the 20-inch decant line with valve control near the downstream toe. The control valve has been buried and maintenance has not been performed since 1977.

### 4.4 WARNING SYSTEM

Although the property is guarded and surrounded by a fence, no formal surveillance or downstream warning system exists. It appears that visits to the embankment only occur very occasionally.

### 4.5 EVALUATION

Formal maintenance procedures do not exist and are not required at the present time. Brush and tree growth should be prevented on the downstream slope, the crest and the upstream slope near the crest. It is recommended that a formal surveillance and downstream warning system be developed for implementation during periods of high or prolonged precipitation.

## SECTION 5 - HYDROLOGY/HYDRAULICS

### 5.1 EVALUATION OF FEATURES

#### A. Design Data

The hydrologic and hydraulic analyses available from the PennDER file for Cornwall Tailings Dam was not very extensive. No frequency curve, unit hydrograph or flood routing was available. There was a stage vs. total volume curve for the reservoir.

#### B. Experience Data

Because of the large storage volume of the reservoir and the small size of the drainage area there has never been a flood problem at this project. Since the mine ceased operation in 1977, the combined effects of the 0.3 cfs of embankment drainage and of the evaporation from the pool have kept the pool contents at a small percentage of the available storage.

#### C. Visual Observations

On the date of the inspection, no conditions were observed that would indicate that the project could not operate satisfactorily during a flood event.

#### D. Overtopping Potential

The calculations in Appendix C indicate that there is a minimum possibility of overtopping. The inflow of one full PMF (Probable Maximum Flood) would raise the existing pool elevation of 890 to about elevation 899, leaving a freeboard of 9 feet. The storage requirements for one PMF is 251 acre-feet, the present storage capacity is estimated at 667 acre-feet or sufficient to store the PMF. Calculations indicate that evaporation and leakage on an annual basis equals the yearly inflow. It is, therefore, considered that overtopping potential does not exist.

#### E. Spillway Adequacy

There is no spillway. The reservoir is considered to be adequate in storage capacity. Annual evaporation and leakage is estimated to be equal to the annual inflow.

The hydrologic analysis for this investigation was based upon existing conditions of the watershed. The effects of future development were not considered.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### A. Visual Observation

##### 1. Embankment

A report prepared by E. D'Appolonia Associates, dated October, 1960 describes the preliminary design considerations for the construction of the embankment. The recommended ratio for the design of the downstream slope was 1.75H to 1V and for the upstream slope 2H to 1V. It was noted that the slope ratios on the downstream slope will stand on slopes of 1.5H to 1V and that the actual slopes will depend on the stability of the rock materials in the slope.

The slope measurements made during this inspection are shown on Plate A-II in Appendix A. This section shows the slope above the uppermost bench to the top of the dam to be 1.7H to 1V, (H = 82'±); the slope to the next lower bench is 1.1H to 1V, (H = 35'±); the next lower slope is 1.4H to 1V, (H = 72'±); and the remainder of the slopes between two narrow benches is 1.5H to 1V (combined H = 15'±). An overall slope line from the top to the downstream toe of the embankment indicates a ratio of 1.95H to 1V.

The elevation of the uppermost bench varies, because this wide bench was used as an access road to the top of the dam from an elevation of about 795.

The visual inspection of the downstream slope did not reveal any evidence of instability. The rock slope surfaces appear to have stabilized with varying slope angles between the 1:1H to 1V and 1:7H to 1V range dependent upon the size of the rock and the amounts of fine stone in a particular area. When considering the dimensions of the entire downstream portion of the embankment, 395±H to 203±V, the benches do not appear to be significant in the evaluation of the slope stability. The overall top to toe slope is flatter than the recommended 1.75H to 1V. This fact, together with the observed conditions indicates that the embankment slopes are stable.

The upstream slope is flatter than 2H to 1V and is also considered to be stable. The crest of the dam has a width of 98 feet rather than the design width of 30 feet.

##### 2. Appurtenant Structures

The only visible part of these structures were two decant towers in the upstream area of the reservoir and the 12-inch outlet of



the drain pipe. All structures appeared to be in good condition. A boat would be required to inspect the tower located in the reservoir. The owner's representative stated that a standpipe was located in this tower on the decant line. The inflow elevation is unknown.

## B. Design and Construction Data

### 1. Embankment

The available engineering data includes a report prepared by E. D'Appolonia Associates. This report describes the details of investigations and engineering calculations that were made regarding seepage and stability of the embankment.

The project was constructed in stages as the waste materials from the mining (iron ore) became available. There are no records of construction of this dam.

The available engineering data indicates that the design was prepared according to accepted engineering data. The stability against sliding, according to the calculations, are well above minimum requirements for safety. The only exception made is that sliding was considered on a horizontal plane, with a maximum dam height of 158 feet (elevation 752 to 910). However, the actual toe of the dam is at elevation 708± and the valley dips nearly 44 feet in 800 feet and no consideration of sliding of the decomposed diabase in a saturated condition was made. The sloping plain will reduce the factor of safety against sliding slightly but is still considered adequate.

### 2. Appurtenant Structures

There is no spillway and it appears that the decant pipe and towers were designed and detailed in accordance with acceptable engineering standards.

## C. Operating Records

Record of operation have not been maintained. Representatives of the owner did not recollect any problems affecting the safety or stability of the structures.

## D. Post Construction Changes

The present embankment has been constructed in stages over a period of 15 years. No changes have been made since the dam was completed in 1977.



E. Seismic Stability

This dam is located in Seismic Zone 1 and it is considered that the static stability is sufficient to withstand minor earthquake induced dynamic forces. No studies or calculations have been made to confirm this assumption.

## SECTION 7 - ASSESSMENT AND RECOMMENDATIONS

### 7.1 DAM ASSESSMENT

#### A. Safety

The visual inspection and the review of available design data indicates that Cornwall Tailings Dam is in good condition and has been designed in accordance with acceptable engineering practice.

Although this dam does not have a spillway, the present storage capacity of the reservoir can handle the PMF without overtopping. The yearly inflow of the small drainage area nearly balances with the expected evaporation and seepage losses and no increase in pool level is expected. The type of embankment with its rock slopes could also withstand some overtopping without endangering the stability. For these reasons, the facilities are considered to be satisfactory.

#### B. Adequacy of Information

The information available for review is considered to be adequate to make a reasonable assessment of these facilities.

#### C. Urgency

It is considered that the recommendations in this section should be implemented as soon as practical.

#### D. Necessity for Additional Studies

Additional studies are not required at this time. However, attention should be given to the recommendations presented below.

### 7.2 RECOMMENDATIONS

#### A. Facilities

There are no special recommendations for the overall facilities. Recommendations are related to operation and maintenance procedures.

#### B. Operation and Maintenance Procedures

The following operations are presented for implementation by the owner:

1. That a staff gauge be installed on the decant tower located in the pool and that at least monthly readings be taken to establish records of changes in the pool level.
2. That the 6-inch blowoff valve on the decant pipe be located and made operable for use in the event of an emergency.
3. That a formal surveillance and downstream warning system be developed for implementation during periods of heavy or prolonged precipitation.

APPENDIX A

CHECKLIST OF VISUAL INSPECTION REPORT

APPENDIX A

CHECK LIST

PHASE I - VISUAL INSPECTION REPORT

PA DER # 38-87

NDI NO. PA-00597

NAME OF DAM Cornwall Tailings Dam HAZARD CATEGORY High

TYPE OF DAM Rockfill with impervious toe section & upstream blanket.

LOCATION Borough of Cornwall ~~TOWNSHIP~~ Lebanon COUNTY, PENNSYLVANIA

INSPECTION DATE 5/11/78 WEATHER Sunny - Warm TEMPERATURE 70's

INSPECTORS: R. Houseal (Recorder)

OWNER'S REPRESENTATIVE(s):

R. Steacy

Charles Neil

A. Bartlett

Ned Kiscadden

H. Jongsma

NORMAL POOL ELEVATION: N/A

AT TIME OF INSPECTION:

BREAST ELEVATION: 908.0 (Estimated)

POOL ELEVATION: 889.7

SPILLWAY ELEVATION: N/A

TAILWATER ELEVATION: 703

MAXIMUM RECORDED POOL ELEVATION: Unknown

GENERAL COMMENTS:

This is not a conventional dam with spillway, outlet, etc. The reservoir was used for storage of silt which was a waste product of iron ore mining.

VISUAL INSPECTION  
EMBANKMENT

	OBSERVATIONS AND REMARKS
A. SURFACE CRACKS	None.
B. UNUSUAL MOVEMENT BEYOND TOE	None.
C. SLOUGHING OR EROSION OF EMBANKMENT OR ABUTMENT SLOPES	None.
D. ALIGNMENT OF CREST: HORIZONTAL: VERTICAL:	Curved and several sharp angles. Not surveyed.
E. RIPRAP FAILURES	None.
F. JUNCTION EMBANKMENT & ABUTMENT OR SPILLWAY	Good.
G. SEEPAGE	Designed for seepage by underdrain to supply minimum flow. About 2 gallon per second from pipe. No seepage from embankment.
H. DRAINS	Lateral and a traverse drain. Two 6-inch pipes about 12 feet above toe. Refer to Appendix F for plans.
J. GAGES & RECORDER	None.
K. COVER (GROWTH)	Waste rock on downstream slope. Upstream slope - silt covered - very flat slope. Several bushes on 100-foot wide crest. Top - grassed area with some fine stones.



VISUAL INSPECTION  
OUTLET WORKS


	OBSERVATIONS AND REMARKS
A. INTAKE STRUCTURE	Two decanter towers tied to 20-inch pipe. Probably only one open.
B. OUTLET STRUCTURE	As near as could be determined in conversation with owner's employees, this structure was vandalized and burned some time ago and was subsequently buried under sand and rock.
C. OUTLET CHANNEL	Natural stream.
D. GATES	None.
E. EMERGENCY GATE	None.
F. OPERATION & CONTROL	None.
G. BRIDGE (ACCESS)	None.


VISUAL INSPECTION  
SPILLWAY

	OBSERVATIONS AND REMARKS
A. APPROACH CHANNEL	None - discharge comes directly from reservoir. Design considered seepage and evaporation as control.
B. WEIR: Crest Condition Cracks Deterioration Foundation Abutments	None.
C. DISCHARGE CHANNEL: Lining Cracks Stilling Basin	None.
D. BRIDGE & PIERS	None.
E. GATES & OPERATION EQUIPMENT	None.
F. CONTROL & HISTORY	None.

VISUAL INSPECTION

	OBSERVATIONS AND REMARKS
<u>INSTRUMENTATION</u>	
Monumentation	None.
Observation Wells	None.
Weirs	None.
Piezometers	None.
Staff Gauge	None.
Other	None.
<u>RESERVOIR</u>	
Slopes	Silt and exposed ground - some trees.
Sedimentation	Silt accumulation (this is the purpose of reservoir)
Watershed Description	Woodland and the reservoir itself.
<u>DOWNSTREAM CHANNEL</u>	
Condition	Small village (Rexmont) downstream.
Slopes	Wooded over 500 feet, then houses.
Approximate Population	100
No. Homes	25





APPENDIX B  
CHECKLIST OF ENGINEERING DATA

APPENDIX B



CHECK LIST  
ENGINEERING DATA

PA DER # 38-87

NDI NO. PA-00 597

NAME OF DAM Cornwall Tailings Dam

ITEM	REMARKS
AS-BUILT DRAWINGS	None.
REGIONAL VICINITY MAP	U.S.G.S. Quadrangle, Lebanon, PA See Plate II, Appendix F
CONSTRUCTION HISTORY	Construction of first phase started in 1961 and completed that year. Contractor - Reisinger Bros., Inc., Carlisle, PA. Embankment raised from original elevation 805 to present elevation 908±.
GENERAL PLAN OF DAM	See Appendix F, Plate III.
TYPICAL SECTIONS OF DAM	See Appendix F, Plate IV.
OUTLETS: PLAN DETAILS CONSTRAINTS DISCHARGE RATINGS	None active at present. This tailings dam had a 20-inch decanter line, which is closed off by a valve near the downstream toe.

ENGINEERING DATA

ITEM	REMARKS
RAINFALL & RESERVOIR RECORDS	None.
DESIGN REPORTS	"Design Consideration" by E. D'Appolinia, Pittsburgh, PA., in PennDER file.
GEOLOGY REPORTS	See report by E. D'Appolinia.
DESIGN COMPUTATIONS: HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None. See report by E. D'Appolinia. See report by E. D'Appolinia.
MATERIALS INVESTIGATIONS: BORING RECORDS LABORATORY FIELD	See Appendix F, Plate VII. See report by E. D'Appolinia. Additional borings in PennDER files.
POST CONSTRUCTION SURVEYS OF DAM	None available.
BORROW SOURCES	Upstream toe formed from material out of reservoir. Main dam formed by trap rock from mine.

ENGINEERING DATA

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	None, except downstream slope was placed on natural slope.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES & REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM  Description:  Reports:	None.
MAINTENANCE & OPERATION RECORDS	None.
SPILLWAY PLAN, SECTIONS AND DETAILS	No spillway.

B-3

ENGINEERING DATA

ITEM	REMARKS
OPERATING EQUIPMENT, PLANS & DETAILS	See Appendix F, Plates III, V and VI. Valve house is presently buried.
CONSTRUCTION RECORDS	Monthly progress records for first phase to elevation 805.
PREVIOUS INSPECTION REPORTS & DEFICIENCIES	None.
MISCELLANEOUS	

# CHECK LIST HYDROLOGIC AND HYDRAULIC ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Small area above reservoir. All wooded.

## ELEVATION:

TOP NORMAL POOL & STORAGE CAPACITY: Elev. 890 62 Acre-Feet

TOP FLOOD CONTROL POOL & STORAGE CAPACITY: Elev. 908 667 Acre-Feet

MAXIMUM DESIGN POOL: Elev. None

TOP DAM: Elev. 908±

## SPILLWAY:

### No Spillway

a. Elevation

b. Type \_\_\_\_\_

c. Width \_\_\_\_\_

d. Length

e. Location Spillover

f. Number and Type of Gates

OUTLET WORKS:

a. Type 20-inch decanter line.

b. Location Left abutment.

c. Entrance inverts 890±.

d. Exit inverts None.

e. Emergency drawdown facilities	6-inch valve on 20-inch line. <del>Buried at present.</del>
----------------------------------	--

## HYDROMETEOROLOGICAL GAGES:

a. Type None.

b. Location

c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: Unknown.

APPENDIX C

HYDROLOGY AND HYDRAULIC CALCULATIONS

APPENDIX C



SUMMARY DESCRIPTION  
OF  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION

The hydrologic and hydraulic evaluation for this inspection report has employed computer techniques using the Corps of Engineers computer program identified as the Flood Hydrograph Package (HEC-1) Dam Safety Version.

The program has been designed to enable the user to perform two basic types of hydrologic analyses: (1) the evaluation of the overtopping potential of the dam, and (2) the capability to estimate the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. A brief summary of the computation procedures typically used in the dam overtopping analysis is shown below.

- Development of an inflow hydrograph to the reservoir.
- Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- Routing of the outflow hydrograph(s) of the reservoir to desired downstream locations. The results provide the peak discharge, time of the peak discharge and maximum stage of each routed hydrograph at the outlet of the reach.

The output data provided by this program permits the comparison of downstream conditions just prior to a breach failure with that after a breach failure and the determination as to whether or not there is a significant increase in the hazard to loss of life as a result of such a failure.

The results of the studies conducted for this report are presented in Section 5.

For detailed information regarding this program refer to the Users Manual for the Flood Hydrograph Package (HEC-1) Dam Safety Version prepared by the Hydrologic Engineering Center, U. S. Army Corps of Engineers, Davis, California.

PROJECT

Dam Investigation

SHEET NO.

Of

SUBJECT

Cerritos Tailings Dam, ID No. 597

COMPUTED BY

RES

DATE

May 29, 1979

CHECKED BY

JPL

Maximum Known Flood

At USGS Gaging Station Back creek near  
Cloona, Max Flood 1963-1976 was 5,150 cfs,  
June '22, 1972, Drainage Area = 7.87 sq. mi.


Estimate maximum inflow to Tailings Dam  
Reservoir

$$\left( \frac{0.16}{7.87} \right)^{0.8} \times 5150 = 230 \text{ cfs } 6-22-72.$$

Estimated surface area of water in  
reservoir.

Over the years, a mixture of tailings  
and water has been introduced to  
the reservoir from various openings  
in a pipe stretched along the  
top of the dam. The tailings  
dropped out of the mixture  
and formed an incline with  
the highest elevation near the  
dam and the lowest at the  
upstream side of the reservoir.  
Water was removed through decant  
towers at the upstream side of  
the reservoir and returned to the  
plant to pick up more tailings.  
The system had been out of  
operation since 1977. At the  
present time there is a pond at  
the upstream side of the  
reservoir which is estimated  
to cover 20 percent of the  
total reservoir area or  $0.2 \times 62 =$   
12 acres. The remaining 50 acres  
is occupied by the inclined fill  
of tailings whose top surface is  
above the level of water surface.  
In 1979, it was  
determined that the present  
pond is at elev. 882.7 (if the top  
of dam is at elev. 908). The top  
of the tailings deposit next to  
the dam is at elev. 904.  
It is estimated that the present pond  
has a maximum depth of 10 feet.


PROJECT Dam Investigation SHEET NO. 1 OF 1  
SUBJECT Cornwall Tailings Dam ID No. PA-577  
COMPUTED BY RES DATE JUNE 1, 1979 CHECKED BY JJPJR



No scale

PROJECT Dam Investigation SHEET NO. 2 OF 2  
 SUBJECT Cornwall Tailings Dam, ID No. 597  
 COMPUTED BY RES DATE May 22, 1979 CHECKED BY JPS

Estimated Surface Area of Water in Reservoir (Cont.)




Estimated Volume of Water in pond on top of tailings deposit

Elev.	Area Acres	Av. Area A:VAIRs	Height Ft	Vol Ac Ft	Total Vol Ac Ft
880	0	0	10	40	0
890	17	21	10	234	40
900	37	48	8	393	274
908	62				667

PROJECT Dam Investigation SHEET NO. 4 OF 4  
 SUBJECT Cornwall Tailings Dam, J.D. No. 111  
 COMPUTED BY RES DATE May 29, 1979 CHECKED BY J.P.J.

Estimated Volume of Water in Pond on  
 Top of Tailings Deposit (Cont.)



Evaporation from Lake Surface

U.S. Weather Bureau Technical Paper No. 37  
 "Evaporation Maps for the United States"  
 Plate 7 "Average Annual Lake Evaporation in  
 Inches" gives 34 inches for this location.

Use 34 inches annually  
 $34 \div 12 = 2.83 \text{ ft annually}$

Seepage from Reservoir

This dam was built about 1961.  
 Information in the files of the owner  
 indicates that measured seepage  
 was 320 gallons per minute or  
 0.71 cfs in 1964.

On May 11, 1979, the seepage flowing  
 from the toe of the dam was  
 measured and found to be 0.3 cfs,  
 = 217,000 gal per day, less this figure.



PROJECT Dam Investigation SHEET NO. 2 OF 2  
 SUBJECT Carroll Tailings Dam, Ill. 30. 577  
 COMPUTED BY RES DATE May 29, 1979 CHECKED BY WOS

### Estimate of Future changes in Water Surface Elevation

The mining operation has been shut down since 1977, and, at the present time, the owner does not expect to add any water to the pond, nor does he expect to drain any water from the pond. The owner's representative reports that the pond has been gradually losing water.

This statement is checked in the calculations below by assuming that the change in pond water volume is equal to the precipitation minus minus the evaporation and minus the seepage. Evaporation is calculated from runoff figures for the USGS gaging station Rock Creek near Elkhart.

### Elkhart Gage

Water Runoff in Year	inches	Water Runoff Year	inches
1964	9.64	1971	13.59
65	4.84	72	27.72
66	4.33	73	19.21
67	9.14	74	15.08
68	12.79	75	17.81
69	9.31	76	19.31
70	14.93	77	16.24
		14) 193.94	
			13.9

Reservoir 62 acres.

Entire basin = .16 Sq. Mi = 102 acres

Wooded area = 102 - 62 = 40 acres (100% Av.)

Use 40 inches runoff for Reservoir (Entire)

(Rainfall x Rock Area) + (Av Runoff x Wooded Area) ÷ Tot. Area = Weighted Runoff

$$\frac{(4.0 \times 62) + (13.9 \times 40)}{102} = 30 \text{ inches - Weighted Runoff}$$

Inches x 53.33 x Sq. Mi. = Ac Ft. of Runoff

$$30 \times 53.33 \times 0.16 = 256 \text{ Ac Ft. Weighted Runoff}$$

\* Runoff from Wooded Area Based on Figure at Silva Gage



Water Year	Inflow Ac. Ft.	Area Acres	Evap. Ac. Ft.	Seepage Ac. Ft.	Yr. End Ac. Ft.	Yr. End Elev.
1978	256	12	34	217	60	889.7
1979	256	12	34	217	65	890.0
1980	256	12	34	217	70	890.8
1981	256	13	37	217	72	891.2
1982	256	14	40	217	71	891.1
1983	256	14	40	217	70	890.8

Evaporation = 2.83 x area in acres.

The above calculations use precipitation and runoff figures for an average year. They show that the pond elevation may be expected to rise a foot or two in a wet year and to fall a foot or two in a dry year. The rise or fall of the pool tends to be self-limiting since a large pool would increase the loss due to evaporation.

At the present level the reservoir has sufficient capacity to hold the runoff from about three average years without any allowance for seepage and evaporation.

This storage capacity can also be expressed as 26 inches of runoff or over three times the 26 inches of runoff some times used as the size of a probable maximum flood.

### Outlet Works (Inoperative)

A 20-inch welded steel decant pipe runs about 1,400 feet from a concrete decant structure in the reservoir to a buried valve 300 feet downstream from the centerline of the dam. At present, there is no flow in this pipe. If a 20-inch tap and valve could be installed\* at this location, water from the reservoir could be discharged into a ditch leading to Bernard Creek. \*(Feasibility of installation would require detailed studies)

calculate maximum discharge:

$$H = \left[ \frac{2.5204(1+K_c)}{D^5} + \frac{466.18 L^2}{D^{16/3}} \right] \left( \frac{Q}{10} \right)^2$$

From levels of 5-11-79 pool level was 889.7

From design drawing, end of 20-inch pipe is at elev. 790.

$$H = 889.7 - 790 = 99.7 \text{ ft.}$$

$$K_c = 0.5$$

$$D = \frac{20}{12} = 1.67 \text{ ft.}$$

$$n = 0.017$$


$$L = 1,400 \text{ ft.}$$

$$\begin{aligned}
 99.7 &= \left[ \frac{2.5204 \times (1.5)}{(1.67)^5} + \frac{466.18 \times (0.017)^2 \times 1400}{(1.67)^{5.33}} \right] \left( \frac{Q}{10} \right)^2 \\
 &= [0.486 + 12.26] \left( \frac{Q}{10} \right)^2
 \end{aligned}$$

$$\left( \frac{Q}{10} \right)^2 = \frac{99.7}{12.75} = 7.82$$

$$\frac{Q}{10} = 2.80 \quad Q = 28 \text{ cfs.}$$

PROJECT DAM SURVEILLANCE SHEET NO. 0 OF 01  
 SUBJECT Cornwall Tailings Dam, I.D. No. 511  
 COMPUTED BY KES DATE May 30, 1979 CHECKED BY JPS



Total Volume in Basin From  
Including Tailings

BASIN STORAGE CURVE  
FROM STATE FILES

BY RLS DATE 6/8/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 9 OF \_\_\_\_\_  
PROJECT D 8490

CORNWALL TAILINGS DAM

## SIZE CLASSIFICATION

MAXIMUM STORAGE = 667 ACRE-FEET

MAXIMUM HEIGHT = 200 FEET

SIZE CLASSIFICATION IS "LARGE"

## HAZARD CLASSIFICATION

VILLAGE OF REXMONT LIES DOWNSTREAM  
OF THIS DAM.

USE "HIGH"

## RECOMMENDED SPILLWAY DESIGN FLOOD

THE ABOVE CLASSIFICATIONS INDICATE USE  
OF AN SDF EQUAL TO THE PROBABLE  
MAXIMUM FLOOD.

BY RLS DATE 6/8/79  
 CHKD. BY \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 10 OF  
 PROJECT D849

CORNWALL TAILINGS DAM

HEC -1 DATA

DRAINAGE AREA = 0.16 SQ. MI.

SUSQUEHANNA BASIN REGION 15B

$$C_p = 0.85$$

$$C_T = 2.20$$

$$L' \text{ END OF RESERVOIR TO BASIN DIVIDE} = 0.23 \text{ MI.}$$

$$T_p = C_T (L')^{.6}$$

$$T_p = 0.9$$

RAINFALL (HMR-33)

$$\text{INDEX (200 SQ. MI. - 24 HR.)} = 23.2 "$$

ZONE 6

INCREMENTAL RAINFALL

$$6 \text{ HR} = 113 \%$$

$$12 \text{ HR} = 123 \%$$

$$24 \text{ HR} = 132 \%$$


$$48 \text{ HR} = 143 \%$$



BY RLS DATE 6/8/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 11 OF  
PROJECT 28490

CORNWALL TAILINGS DAMCAPACITY CURVE



## FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 26 FEB 79

\*\*\*\*\*

1	A1	CORNWALL TAILINGS DAM **** BERNHARD CREEK									
2	A2	BOROUGH OF CORNWALL, LEBANON COUNTY, PA.									
3	A3	NDI # PA-00597 PA DER # 38-87									
4	B	300	0	15	0	0	0	0	0	-4	0
5	B1	5									
6	J	1	9	1							
7	J1	1	.85	.7	.6	.5	.4	.3	.2	.1	
8	K		1					1			
9	K1	INFLOW HYDROGRAPH									
10	M	1	1	.16							1
11	P	23.2	113	123	132	143					
12	T							.1	.05		
13	W	.9	.85								
14	X	-1.5	-.05	2							
15	K	1	2					1			
16	K1	RESERVOIR ROUTING									
17	Y			1	0						
18	Y1	1						40	-1		
19	Y4	908	908.1	908.2	908.3	908.4	908.5	908.6	908.8	909	
20	Y5	0	324	918	1686	2596	3627	4768	7341	10260	
21	Y6	0	40	274	667	730					
22	Y7	880	890	900	908	909					
23	Y8	908									
24	Y9	908									
25	K	99									

## PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	1
ROUTE HYDROGRAPH TO	2
END OF NETWORK	

\*\*\*\*\*

## FLOOD HYDROGRAPH PACKAGE (HEC-1)

DAM SAFETY VERSION JULY 1978

LAST MODIFICATION 26 FEB 79

\*\*\*\*\*

RUN DATE: 79/06/07.

TIME: 07.18.28.

CORNWALL TAILINGS DAM \*\*\*\* BERNHARD CREEK

BOROUGH OF CORNWALL, LEBANON COUNTY, PA.

NDI # PA-00597 PA DER # 38-87

## JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
300	0	15	0	0	0	0	0	-4	0
			JOFER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRTIO= 9 LRTIO= 1

RTIOS= 1.00 .85 .70 .60 .50 .40 .30 .20 .10

CORNWALL TAILINGS DAM \*\*\* BERNHARD CREEK  
BOROUGH OF CORNWALL, LEBANON COUNTY, PA.  
NDI # PA-00597 PA DEF # 38-87

JOB SPECIFICATION  
NO NHR NMIN IDAY IHR IMIN METRC IPLT IPRT NSTAV  
300 0 15 0 0 0 0 0 -4 0  
JOFR NWT LROPT TRACE  
5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
NPLAN= 1 NRTIO= 9 LRTIO= 1  
RTIOS= 1.00 .85 .70 .60 .50 .40 .30 .20 .10

\*\*\*\*\*

# SUB-AREA RUNOFF COMPUTATION

## INFLOW HYDROGRAPH

ISTAQ ICOMP IECON ITAPE JFLT JPRT INAME ISTAGE IAUTO  
1 0 0 0 0 0 1 0 0

HYDROGRAPH DATA  
IHYDG IUNG TAREA SNAP TRSDA TRSFC RATIO ISNOW ISAME LOCAL  
1 1 .16 0.00 .16 0.00 0.000 0 1 0

PRECIP DATA  
SPFE PMS R6 R12 R24 R48 R72 R96  
0.00 23.20 113.00 123.00 132.00 143.00 0.00 0.00  
TRSFC COMPUTED BY THE PROGRAM IS .800

LOSS DATA  
LROPT STRKR DLTNR RTIOL ERRAIN STRNS RTIOK STRTL CNSTL ALSHX RTIMP  
0 0.00 0.00 1.00 0.00 0.00 1.00 1.00 .05 0.00 0.00

UNIT HYDROGRAPH DATA  
TP= .90 CP= .85 NTA= 0

RECESSION DATA  
STRTO= -1.50 ORCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH 9 END-OF-PERIOD ORDINATES, LAG= .90 HOURS, CP= .84 VOL= 1.00  
15. 48. 80. 95. 85. 54. 23. 9. 3.

END-OF-PERIOD FLOW  
NO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q NO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q

SUM 26.54 24.13 2.41 10216.  
( 674.)( 613.)( 61.)( 289.28)

\*\*\*\*\*

## HYDROGRAPH ROUTING

\*\*\*\*\*

# HYDROGRAPH ROUTING

## RESERVOIR ROUTING

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0

## ROUTING DATA

QLOSS	CLOSS	AVG	IRCS	ISAME	IOPT	IFHP	LSTR
0.0	0.000	0.00	1	0	0	0	0

NSTPS	NSTDL	LAG	AMSK	X	TSK	STORA	ISFRAT
1	0	0	0.000	0.000	0.000	40.	-1

STAGE	908.00	908.10	908.20	908.30	908.40	908.50	908.60	908.80	909.00
-------	--------	--------	--------	--------	--------	--------	--------	--------	--------

FLOW	0.00	324.00	918.00	1686.00	2596.00	3627.00	4768.00	7341.00	10260.00
------	------	--------	--------	---------	---------	---------	---------	---------	----------

CAPACITY=	0.	40.	274.	667.	730.
-----------	----	-----	------	------	------

ELEVATION=	880.	890.	900.	908.	909.
------------	------	------	------	------	------

CREL	SPWID	COGW	EXPW	ELEV	COOL	CAREA	EXPL
908.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

## DAM DATA

TOPEL	COORD	EXPD	DAMWID
908.0	0.0	0.0	0.

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

PEAK OUTFLOW IS 0. AT TIME 0.00 HOURS

of the tailings dam is at (elev. 904).  
 It is estimated that the dam core has a maximum depth of 10 feet.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS													
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)													
AREA IN SQUARE MILES (SQUARE KILOMETERS)													
OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS									
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9	
				1.00	.85	.70	.60	.50	.40	.30	.20	.10	
HYDROGRAPH AT	1	.16 (.41)	1	758.	644.	531.	455.	379.	303.	227.	152.	76.	
				( 21.47)(	18.25)(	15.03)(	12.88)(	10.73)(	8.59)(	6.44)(	4.29)(	2.15)	
ROUTED-TO	2	.16 (.41)	1	0.	0.	0.	0.	0.	0.	0.	0.	0.	
				( 0.00)(	0.00)(	0.00)(	0.00)(	0.00)(	0.00)(	0.00)(	0.00)(	0.00)	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
ELEVATION		890.00		908.00		908.00	
STORAGE		40.		667.		667.	
OUTFLOW		0.		0.		0.	
RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	899.03	0.00	251.	0.	0.00	0.00	0.00
.85	897.67	0.00	220.	0.	0.00	0.00	0.00
.70	896.32	0.00	188.	0.	0.00	0.00	0.00
.60	895.42	0.00	167.	0.	0.00	0.00	0.00
.50	894.51	0.00	146.	0.	0.00	0.00	0.00
.40	893.61	0.00	125.	0.	0.00	0.00	0.00
.30	892.71	0.00	103.	0.	0.00	0.00	0.00
.20	891.81	0.00	82.	0.	0.00	0.00	0.00
.10	890.90	0.00	61.	0.	0.00	0.00	0.00

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*  
 EOI ENCOUNTERED.  
 NX



APPENDIX D  
GEOLOGIC REPORT

APPENDIX D

## GEOLOGIC REPORT

### Bedrock - Dam and Reservoir

Formation Names: Hammer Creek Formation and Diabase.

Lithology: Predominantly red to brown quartz sandstone with interbeds of quartz pebble conglomerate and some red shale. The sandstone beds are typically a few inches to a foot, or more, thick. Grain size ranges from very fine to coarse. Sand grains are angular to sub-rounded quartz, imbedded in a matrix of clay and hematite. The conglomerates consist of pebbles and cobbles of quartzite, vein quartz and sandstone in a matrix of coarse sandstone, clay and hematite. The shale beds are red, thin bedded, non-fissile, composed of clay, hematite and some calcite.

Diabase is an intrusive igneous rock composed essentially of pyroxene and feldspar. Quartz, ilmenite and magnetite are common accessory minerals. The fresh rock is gray to dark gray with massive crystalline texture. Weathered surfaces are dark gray with local brown iron staining. The interlocking crystals of pyroxene and feldspar make the rock very tough and strong.

### Structure

At the dam site, beds of the Hammer Creek Formation which strike N55°E and dip 20° to 25°NW, have been intruded by a diabase dike. The geologic map of the Lebanon Quadrangle (see map) shows a major diabase sheet just north of the dam. This sheet dips to the south at about 30°, but the upper surface has many irregularities. Exploration drilling for the dam found diabase to be present under the lower slopes of the valley. This is probably a continuation of the small mass shown in the tailings pond area on the geologic map. The mass is apparently a dike offshoot of the main diabase sheet. The dike approximately parallels the valley, and is probably responsible for the mapped fracture trace. There are no faults mapped in the area, but faults are known nearby, thus offsetting both the Hammer Creek and diabase formation.

### Overburden

The sides of the valley were covered with colluvium derived from the Hammer Creek Formation, mostly sand and conglomerate boulders with some weathered shale. This was from 0 to 10 feet thick. In the center of the valley this colluvium covered the decomposed and weathered diabase.



### Aquifer Characteristics

Diabase is a very impermeable rock. Ground water movement is entirely along joints and other fractures. The Hammer Creek beds are also relatively impermeable, ground water moves almost entirely along bedding planes and fractures. Tests made in the drill holes indicated that the weathered diabase was more permeable than the decomposed diabase. This means that there is a relatively permeable zone sandwiched between the decomposed diabase (near surface) and the fresh diabase; (depths of 17 to 30 feet).


### Discussion

This dam was not constructed to impound water, but to hold tailings. It therefore, has a drain rather than a cutoff trench. It can only be commented that the decomposed diabase has a high clay content, and that the underlying permeable zone could keep that clay wet and therefore, susceptible to slippage.


### Sources of Information

1. Lapham, D.M. and Gray, C. (1972). "Geology and Origin of the Triassic Magnetite Deposit at Cornwall, Pa.". Pa. Geological Survey, Bulletin M56.
2. Air Photographs, dated 1969. Scale 1:20,000.
3. Core boring data in file.


# GEOLOGIC MAP - Tailings Dam




(geology from Pa. Geol. Surv. Report M-56)




diabase




Hammer Creek Fm.- sandstone and shale



Hammer Creek Fm.- conglomerate lenses



Mill Hill Slate



Buffalo Springs Fm.




fault



air photo fracture trace

SCALE 1:24,000



APPENDIX E  
PHOTOGRAPHS

APPENDIX E



Top of Dam  
Looking to  
Left Abutment




Downstream Slope




View from top of  
dam towards  
decant towers

PA-597  
Plate E-1



Reservoir with decant towers.  
Dam in background



Detail of Decant Tower

PA-597  
Plate E-II



Reservoir - Dam in background



Looking downstream from top of dam


PA-597  
Plate E-III




APPENDIX F

PLATES

APPENDIX F







Wave House  
See enlarged detail


50 FEET WIDE BENCH  
ELEV. 720

5 FEET WIDE BENCH  
ELEV. 850

GRADE BREAK


EMBANKMENT  
CREST ELEV. 810  
SIDE SLOPE 2 H:1

APPROXIMATE AREA OF RESERVOIR 62.5 ACRES  
APPROXIMATE CAPACITY 6,500,000 CU FT










ENLARGED PLAN OF VALVE HOUSE  
Scale 1"=50'

4" Gate valve  
50-16 eccentric redam  
16" Decant pipe  
4" Gate valve  
6" Drain



SECT. A-A

ELEVATION B-B

Note:

The capacity of the Reservoir at 21.901' w. full is sufficient to contain 7,315,000 gal. of water, assuming densities reported by Dapollon Associates (1976) and shown on SK 157-06. Adjustments for Crest elevation must be made on basis of actual conditions.




- TEST PIT
- ◆ DIAMOND DRILL HOLES
- WATER TESTED O.B. HOLES


S-555 TOPOGRAPHY AT DAM SITE	
NO.	REFERENCES
1	GENERAL PLAN & REFLECT PLANS
2	GENERAL PLAN & TOPOGRAPHY
3	GENERAL PLAN & TOPOGRAPHY
4	GENERAL PLAN & TOPOGRAPHY
5	GENERAL PLAN & TOPOGRAPHY
6	GENERAL PLAN & TOPOGRAPHY
7	GENERAL PLAN & TOPOGRAPHY
8	GENERAL PLAN & TOPOGRAPHY
9	GENERAL PLAN & TOPOGRAPHY
10	GENERAL PLAN & TOPOGRAPHY
11	GENERAL PLAN & TOPOGRAPHY
12	GENERAL PLAN & TOPOGRAPHY
13	GENERAL PLAN & TOPOGRAPHY
14	GENERAL PLAN & TOPOGRAPHY
15	GENERAL PLAN & TOPOGRAPHY
16	GENERAL PLAN & TOPOGRAPHY
17	GENERAL PLAN & TOPOGRAPHY
18	GENERAL PLAN & TOPOGRAPHY
19	GENERAL PLAN & TOPOGRAPHY
20	GENERAL PLAN & TOPOGRAPHY
21	GENERAL PLAN & TOPOGRAPHY
22	GENERAL PLAN & TOPOGRAPHY
23	GENERAL PLAN & TOPOGRAPHY
24	GENERAL PLAN & TOPOGRAPHY
25	GENERAL PLAN & TOPOGRAPHY
26	GENERAL PLAN & TOPOGRAPHY
27	GENERAL PLAN & TOPOGRAPHY
28	GENERAL PLAN & TOPOGRAPHY
29	GENERAL PLAN & TOPOGRAPHY
30	GENERAL PLAN & TOPOGRAPHY
31	GENERAL PLAN & TOPOGRAPHY
32	GENERAL PLAN & TOPOGRAPHY
33	GENERAL PLAN & TOPOGRAPHY
34	GENERAL PLAN & TOPOGRAPHY
35	GENERAL PLAN & TOPOGRAPHY
36	GENERAL PLAN & TOPOGRAPHY
37	GENERAL PLAN & TOPOGRAPHY
38	GENERAL PLAN & TOPOGRAPHY
39	GENERAL PLAN & TOPOGRAPHY
40	GENERAL PLAN & TOPOGRAPHY
41	GENERAL PLAN & TOPOGRAPHY
42	GENERAL PLAN & TOPOGRAPHY
43	GENERAL PLAN & TOPOGRAPHY
44	GENERAL PLAN & TOPOGRAPHY
45	GENERAL PLAN & TOPOGRAPHY
46	GENERAL PLAN & TOPOGRAPHY
47	GENERAL PLAN & TOPOGRAPHY
48	GENERAL PLAN & TOPOGRAPHY
49	GENERAL PLAN & TOPOGRAPHY
50	GENERAL PLAN & TOPOGRAPHY
51	GENERAL PLAN & TOPOGRAPHY
52	GENERAL PLAN & TOPOGRAPHY
53	GENERAL PLAN & TOPOGRAPHY
54	GENERAL PLAN & TOPOGRAPHY
55	GENERAL PLAN & TOPOGRAPHY
56	GENERAL PLAN & TOPOGRAPHY
57	GENERAL PLAN & TOPOGRAPHY
58	GENERAL PLAN & TOPOGRAPHY
59	GENERAL PLAN & TOPOGRAPHY
60	GENERAL PLAN & TOPOGRAPHY
61	GENERAL PLAN & TOPOGRAPHY
62	GENERAL PLAN & TOPOGRAPHY
63	GENERAL PLAN & TOPOGRAPHY
64	GENERAL PLAN & TOPOGRAPHY
65	GENERAL PLAN & TOPOGRAPHY
66	GENERAL PLAN & TOPOGRAPHY
67	GENERAL PLAN & TOPOGRAPHY
68	GENERAL PLAN & TOPOGRAPHY
69	GENERAL PLAN & TOPOGRAPHY
70	GENERAL PLAN & TOPOGRAPHY
71	GENERAL PLAN & TOPOGRAPHY
72	GENERAL PLAN & TOPOGRAPHY
73	GENERAL PLAN & TOPOGRAPHY
74	GENERAL PLAN & TOPOGRAPHY
75	GENERAL PLAN & TOPOGRAPHY
76	GENERAL PLAN & TOPOGRAPHY
77	GENERAL PLAN & TOPOGRAPHY
78	GENERAL PLAN & TOPOGRAPHY
79	GENERAL PLAN & TOPOGRAPHY
80	GENERAL PLAN & TOPOGRAPHY
81	GENERAL PLAN & TOPOGRAPHY
82	GENERAL PLAN & TOPOGRAPHY
83	GENERAL PLAN & TOPOGRAPHY
84	GENERAL PLAN & TOPOGRAPHY
85	GENERAL PLAN & TOPOGRAPHY
86	GENERAL PLAN & TOPOGRAPHY
87	GENERAL PLAN & TOPOGRAPHY
88	GENERAL PLAN & TOPOGRAPHY
89	GENERAL PLAN & TOPOGRAPHY
90	GENERAL PLAN & TOPOGRAPHY
91	GENERAL PLAN & TOPOGRAPHY
92	GENERAL PLAN & TOPOGRAPHY
93	GENERAL PLAN & TOPOGRAPHY
94	GENERAL PLAN & TOPOGRAPHY
95	GENERAL PLAN & TOPOGRAPHY
96	GENERAL PLAN & TOPOGRAPHY
97	GENERAL PLAN & TOPOGRAPHY
98	GENERAL PLAN & TOPOGRAPHY
99	GENERAL PLAN & TOPOGRAPHY
100	GENERAL PLAN & TOPOGRAPHY

PA. 597  
PLATE III







SECTION 1-1  
E STA 4+00




SECTION 2-2  
E STA 6+80




SECTION 3-3  
E STA 11+20






SECTION 3-3  
STA. 10+80



SECTION 4-4  
STA. 14+80




2




1087-51 GENERAL PLAN TAILINGS DAM		NO.	BY	DATE
REFERENCE	REFERENCE TITLE	REVISIONS		
DWG. NO.	CORNWALL MILL & PELLET PLANT			
TYPICAL CROSS-SECTIONS OF TAILINGS DAM				
CORNWALL DIVISION				
BETHLEHEM MINERALS COMPANY				
OPERATED BY				
BETHLEHEM CORNWALL CORPORATION				
BETHLEHEM, PA.				
DRAWN	FE-67	CHECKED	DATE	ORDER
TRACED	12-1-66	DATE	12-1-66	ORDER
APPROVED	12-1-66	DATE	12-1-66	ORDER
NO. 1087-51-5				

PA.  
PL.



SECTION 3-3  
STA. 10+80



TYPICAL CROSS-SECTION OF WING


2



1057-51		GENERAL PLAN TAILINGS DAM			
REFERENCE DWS NO.	REFERENCE TITLE		NO.	BY	DATE
			REVISIONS		
CORNWALL MILL & PELLET PLANT					
TYPICAL CROSS-SECTIONS OF TAILINGS DAM					
CORNWALL DIVISION					
BETHLEHEM MINERALS COMPANY					
OPERATED BY					
BETHLEHEM CORNWALL CORPORATION					
BETHLEHEM, PA.					
DRAWN: E.C.D. 1/2/51		CHECKED: J.H. 1/2/51		SCALE: 1"=50'	
TRACED: J.H. 1/2/51		DATE: 12-3-50		CORNWALL 1057-51	
APPROVED: J.H. 1/2/51		NO. 1057-51			

3

PA-597  
PLATE IV




LIST OF REINFORCING BARS: ONE TON


Species	Sex	Stage	Count
"	♂	10 cc	3
"	♂	15 cc	4
"	♂	8 cc	2
"	♂	12 cc	3
"	♂	15 cc	4 x 5
"	♂	12 cc	2 x 3
"	♂	15 cc	4
"	♂	12 cc	2 x 3 x 5
"	♂	15 cc	4
"	♂	12 cc	2 x 3
"	♂	15 cc	4
"	♂	12 cc	2 x 3
"	♂	15 cc	4 x 5








PROFILE OF DAMANT LINE  
Scale 1" = 50'




SECT C-C



DETAIL OF TOWER SCREEN

3 Reg'd

Scale 1" = 10'



SECT B-B



DETAIL OF STEP LOG



46 Reg'd

Note: Tower shall be poured as a monolith. When the tower is to be abandoned, the wall shall be moved to next tower. The abandoned tower shall be filled with a blind flange and tower pit filled with concrete to 1' above the blind flange. See detail.


PA. 597  
PLATE V

PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597
PA. 597	PA. 597	PA. 597	PA. 597	PA. 597	PA. 597






DETAIL OF TOWER SCREEN  
3 Reg'd  
Scale 1/4" = 1'-0"



SECT. A-A



DETAIL OF TOWER LOG  
45 Reg'd

Note Tower shall be poured as a monolith.  
When one Tower is to be abandoned, the inlet Bell shall  
be moved to next Tower. The abandoned one shall be  
sealed with a blind flange and Tower pit filled with  
lean concrete to 2' above the blind flange of  
the Bell.


PA. 597  
PLATE V


DATE	BY	CHECKED	APPROVED
1942-10-10	J. H. H. H.	J. H. H. H.	J. H. H. H.
PA. 597			
DETAILS OF TOWER SCREEN			
DETAILS OF TOWER LOG			
CORNWALL DIVISION			
BETHLEHEM MINERALS COMPANY			
BETHLEHEM CORNWALL CORPORATION			
















D.H. 30 DA

EL. 828


Depth BPF

Core %

Rec'd Rec.

0'	2	Brown sandy clay & gravel
4'	14	Brown clay & cg frags
70'	200	Silty sandstone fragments
		Good cong Bottom of run is shale
100'	55%	Badly broken mottled red shale
EL. 800		No core 25-28 Balance badly broken sandstone
32' 6" 9"	66%	
38' 6" 9"	26%	Badly broken conglomerate
44' 7" 0"	100%	Same
50' 3" 0"	60%	Cong. 1st 11" and last 8" badly broken. Bal. solid
52' 1" 11"		Dark gray broken sandstone
58' 3" 6"	100%	Top 29" dark very fg. Ss Bal is broken gray Ss
60' 4" 6"	100%	Hard red gray Ss. Last 1' broken
66' 6" 0"	100%	Ss. to 62' 6", then cong. all broken
71' 5" 0"	100%	First 4' mottled red shale - then sandstone
EL. 750		Sandstone - broken 76'-77'
77' 6" 0"	100%	
85' 5" 0"	100%	Hard mottled red shale
85' 1" 7"	53%	Mottled red shale
88' 3" 0"	100%	Cong. - little shale upper 3' badly broken
89' 2" 0"	100%	Ss & shak. last 5' badly broken
		No core
97' 5" 11"	99%	Gray sandstone Broken 91-93 & 95'-96'
100' 3" 0"	100%	Conglomerate
104' 3" 0"	100%	Cong. little indication diabase mineralization
108' 4" 0"		Cong. less diabase staining Ss 104' 104.9'
110' 3" 6"	100%	Conglomerate. Good core
		Conglomerate. weathered zones
EL. 700		112-114, 117-118 and 124-124.6'
126' 30" 6"	100%	
		Approx
		Gray sandstone - weathered & broken
169' 27" 6"	100%	No Core
172' 2" 6"	83%	
177'		No core
179' 180' 9" 8"	100%	Weathered & decomposed diabase
		Good core - weathered diabase

contact of diabase with M



- Sandstone
- Conglomerate
- Shale
- Diabase

2



B.P.F.  
%  
Rec.

- 7 Sandy clay
- 11 Decomposed diabase
- 15 Same, sandy with cong. pebbles
- 19 Decomposed diabase
- 21 Same with sand & cg pebbles

Diabase good 24'-29' Some weathering  
29-30, 32'-32.6, 35'-36, 37'-38.

100%  
100% Good diabase

D.H. 32 D'A  
E1 731'

Depth B.P.F.  
Core %  
Recrs Rec.

0'	4	Sandy clay (Dry)
4'	12	Sdy clay decomposed diab
6'	18	Decomposed diabase
9'	180	Same
14'	225	Same
19'	No core	No core
20'	358	Decomposed - diabase
24'	No core	No core
27' 1'0"	839	Weathered diabase
29' 2'0"	100%	Same
34' 5'6"	100%	Diabase - Weathered 30'
42' 6'5"	86%	Diabase
55' 10'7"	100%	Good solid diabase. Weather

D.H. 33 D'A  
E1.747

Depth B.P.I  
Core %  
Recrd Rec

1 Sandy clay (Dry)  
2 Sdy clay decomposed diabase  
3 Decomposed diabase  
4 Same  
5 Same  
6 No core  
7 Decomposed - diabase  
8 No core  
9 Weathered diabase  
10 Same  
11 Diabase Weathered 30'-32'6"  
12 Diabase  
13 Good solid diabase. Weathered 42'-43'

Hole stopped

PA. 597  
PLATE VII


Note:

Blows per foot-spoon samples and % core recovered are shown in the same column. Drill hole elevations are from Map 224 pl. 4 and may vary a few feet from levels run to holes.

PA. 597  
PLATE III

D.H. 31 DA  
El. 763


Depth B.P.F.  
Core %  
Rec'd Rec.



Hole stopped

D.H. 32 DA  
El. 731

Depth B.P.F.  
Core %  
Rec'd Rec.



DH 33 DA  
E1.747

32 DA  
731'

Depth BPF  
Core %  
Recrd Rec

0'	4	Sandy clay (Dry)
4'	12	Sdy clay decomposed diabase
6'	18	Decomposed diabase
9'	180	Same
19'	225	Same
20'	958	No core
24'	958	Decomposed - diabase
27'	1'0"	No core
29'	939	Weathered diabase
32'	2'0"	Same
34'	5'5"	Diabase - Weathered 30'-32'6"
42'	6'5"	Diabase
53'	10'7"	Good solid diabase. Weathered 42'-43'
		100%

Depth BPF  
Core %  
Recrd Rec

0'	5	So
5'	14	So.
10'	15	So.
12'	11	Rec
15'	175	500
33' 9"	56%	Good
40' 7"	100%	

Hole stopped

Note:

Blows per foot spoon samples and % core recovered are shown in the same column. Drill hole elevations are from Map 224 pl 4 and may vary a few feet from levels run to holes.

B.P.F.  
%  
Rec

- 5 Sandy clay
- 14 Same with cong pebbles
- 15 Same
- 11 Decomposed diabase
- 175 ~~Same~~

Diabase somewhat weathered & broken  
Most weathered at 27'

Presumed contact of diabase with Me

56%  
100% Good diabase

3

ore  
d may



D.H. 34DA

El. 832

Depth BPF  
Core %  
Recvd Rec

0	3	Sandy clay & cong fragments
3	19	Same
8	15	Clay, silt, sand & cg frags. (Dry)
12	31	Clay, silt, cg frags. (Moist)
17	12	Soft red shale
22	27	Same
27	200	Same

Mainly mottled red shale. Ss layer at 35'-38' and 41'-42' Very badly broken.

42' 6.9" 47%

Mainly cong. Broken 49'-51' Considerable weathering in spots

52' 9.6" 100%

Mottled red shale. Last 1' is sandstone, soft in spots.

58' 2.0" 100%

Badly broken sandstone

61' 3.2" 91%

Conglomerate - good core

63' 1.2" 78%

Badly broken mottled red shale

68' 2.6" 50%

Same

72' 2.0" 46%

Badly broken sandstone

78' 3.5" 38%

Broken cong. Last 1' is hard red gray sandstone

82' 6.0" 100%

Mainly very badly broken Ss. with thin cg. streaks

87' 5.0" 100%

First part cong - last 8" badly broken - then shale

91' 3.6" 88%

First 4" mottled red shale - then thin

lenses cong & Ss. All broken

Hole stopped

with Mesozoic sediments

4

SECTION  
THROUGH

DRILL HOLES 30DA, 31DA, 32DA, 33DA & 3  
PROPOSED TAILINGS DAM

CORNWALL

SCALE 1" = 20'

0 10' 20' 40'

DA

BPF

ve %  
cnd Rec

- 3 Sandy clay & cong fragments
- 19 Same
- 15 Clay, silt, sand & cg frags. (Dry)
- 31 Clay, silt, cg frags. (Moist)
- 12 Soft red shale
- 27 Same
- 200 Same

EL. 800'

Mainly mottled red shale. Ss layer  
at 35'-38' and 41'-42' Very badly broken.

- 3" 47% Mainly cong. Broken 49'-51'
- Considerable weathering in spots
- 6" 100% Mottled red shale. Last 1' is sandstone, soft
- 10" 26% in spots
- 10" 100% Badly broken sandstone
- 12" 91% Conglomerate. good core
- 12" 78% Badly broken mottled red shale
- 16" 50% Same
- 10" 46% Badly broken sandstone
- 15" 38% Broken cong. Last 1' is hard red gray sandstone
- 10" 100% Mainly very badly broken Ss. with thin cg streaks EL 750'
- 10" 100% First part cong - last 8' badly broken - then shale
- 16" 88% First 4' mottled red shale - then thin  
lenses cong & Ss. All broken

topped

EL. 700'

SECTION  
THROUGH  
HOLES 30DA, 31DA, 32DA, 33DA & 34DA  
PROPOSED TAILINGS DAM

CORNWALL

SCALE 1" = 20'

0' 10' 20' 40'

PA. 597  
PLATE VIII